

AGENDA CITY COUNCIL WORKSHOP 7651 E. Central Park Ave. Bel Aire. KS

7651 E. Central Park Ave, Bel Aire, KS Video Available at <u>belaireks.gov</u> September 12, 2023 6:30 PM



I. CAPITAL IMPROVEMENTS

- A. Parks Master Plan
- <u>B.</u> Pool
- C. Public Works Facility

II. OTHER?

III. DISMISS

Additional Attachments

A. Manager's Report - September 12, 2023

Notice

It is possible that sometime between 6:00 and 6:30 PM immediately prior to this meeting, during breaks, and directly after the meeting, a majority of the Governing Body may be present in the Council Chambers or the lobby of City Hall. No one is excluded from these areas during these times. Video of this meeting can be streamed at www.belaireks.gov and on YouTube. Please make sure all cell phones and other electronics are turned off and put away.



0000

3 Parks Master Plan City of Bel Aire, KS City Council Workshop

September 12th, 2023











AGENDA

Initiation

Discovery

Analysis

Implementation

Recommendations



Bel Aire

Established 1980






INITIATION

Community Profile


9.3%

Poverty

Population Population in Median Age 34.2









90,957 **Median Household** Income







Section I, Item A.

96.2% High School Graduate or higher







4

DISCOVERY

Assessments

Recreation Complex? If "Yes," how satisfied are you? Answered: 289 Skipped: 57



| | POOR | (NO LABEL) | GOOD | (NO LABEL) | EXCELLENT | N/A | TOTAL | WEIGHTED AVERAGE |
|---|------------|---------------|-------------|---------------|------------|---------------|-------|---------------------|
| ☆ | 1.38% 4 | 1.04% 3 | 3.81% 11 | 2.42% 7 | 1.73% 5 | 89.62% 259 | 289 | 3.20 |

Citizens Survey

Q21: Do you or other members of your household use the playground at the Recreation Complex? If "Yes," how satisfied are you?

Answered: 292 Skipped: 54

Park Inventory

Open House



Q20: Do you or other members of your household play flag football at the

Bel Aire, Kansas - Parks Master Plans

Parks and Recreation Asset Assessment Tool

Accessibility

Criterion Score: <u>14</u>

Ease in Walking to Park

1 being a park with poor access to and from adjacent streets or neighborhoods due to lack of sidewalks, shade trees, or limited street crossings, versus **5** being ADA accessible on shaded sidewalks with pedestrian street crossings, an interconnected sidewalk system, and multiple street frontages



Clarity of Signage

<u>1</u> being a park without any signage identifying it as a Bel Aire Park versus <u>5</u> being a park utilizing new signage clearly identifying it as a Bel Aire Park.



Reduction of Weather Impacts

1 being a park which provides no structures, natural shade, or protection from the wind, rain, and sun, versus **5** being a park which offers an easily accessible covered structure, shaded playground equipment or bleachers, or numerous shade trees providing complete coverage and protection from the elements.



ADA Compliance

<u>1</u> being a park that offers no accessible routes between park elements, versus <u>5</u> being a park that offers clear ADAcompliant routes between all amenities.



Comments or Observations:

| Section I, Item A. | |
|--------------------|--|
| | |
| | |

ASSESSMENT Bel Aire Park



| Accessibility: | 15/20 |
|----------------------|-------|
| Comfort & Character: | 30/35 |
| Usability: | 13/15 |
| Amenities: | 21/30 |








ASSESSMENT Bel Aire Recreation Complex




| Accessibility: | 11/20 |
|----------------------|-------|
| Comfort & Character: | 32/35 |
| Usability: | 12/15 |
| Amenities: | 24/30 |



ASSESSMENT Central Park



| Accessibility: | 10/20 |
|----------------------|-------|
| Comfort & Character: | 30/35 |
| Usability: | 12/15 |
| Amenities: | 24/30 |










Citizen Survey

CITIZEN SURVEY 35-45 **CENTRAL PARK TOP AMENITIES OFFERED** WALKING TRAIL PLAYGROUND **DESIRED AMENITIES** PICNIC SHELTERS SPLASH PAD

RESPONSE TIME: 2/24/23 - 4/19/23 NUMBER OF RESPONSES: 346





Section I, Item A.



ANALYSIS

Open House

What Did We Hear?

Bel Aire Recreation Complex

- -Recreation Building Expansion
- -Diamond Field Improvements
- -Tennis

Bel Aire Park

- Restroom
- Parking
- Added Play Equipment


Central Park

- Pool
- Pickleball
- Pond Activation










- 5 | TENNIS + PICKLE BALL COURT
- 41 RECTANGULAR FIELD 4 | STAGE/PLAZA
- MAJORS LEAGUE DIAMOND FIELD
- | EXTENDED EXISTING PLAYGROUND
- I | BUILDING EXPANSION
 - 8 | DESTINATION PLAYGROUND 9 | BASKETBALL COURT
- EXISTING SHELTER

12 | RESTROOM/CONCESSIONS

SOCCER FIELDS



Section I, Item A.



RECOMMENDATIONS Bel Aire Park

- Increase usability for residents
- Remove sand play and tennis
- New playground, restrooms, and parking

cost estimate

| DEMO | \$50,000 |
|-------------------|-----------|
| PAVEMENT | \$100,000 |
| PARKING | \$30,000 |
| MEDIUM PLAYGROUND | \$500,000 |
| RESTROOM | \$250,000 |
| SITE FURNISHINGS | \$10,000 |
| LANDSCAPE | \$10,000 |
| TOTAL | \$950,000 |



RECOMMENDATIONS Bel Aire Recreation Complex

- Keep up with the needs of the community
- Building remodel, expansion, or both
- Add destination playground
- Add multi-sport play
- Activate shelter area

cost estimate

| DEMO | \$80,000 |
|-----------------------------|-------------|
| PAVEMENT | \$550,000 |
| BUILDING IMPROVEMENTS | |
| DESTINATION PLAYGROUND | \$800,000 |
| EXISTING PLAYGROUND UPDATES | \$60,000 |
| PLAZA | \$500,000 |
| DOG PARK | \$50,000 |
| ATHLETICS | \$300,000 |
| SITE FURNISHING | \$50,000 |
| LANDSCAPE | \$15,000 |
| TOTAL | \$3,762,000 |





RECOMMENDATIONS

Central Park

- Activate!
- Add Pickleball
- Add Shelters
- Add fishing docks
- Add play elements
- Add restroom
- Add parking
- Capture revenues
- Leaves flexibility


cost estimate

| PARKING | \$20,000 |
|---------------------|-------------|
| PAVEMENT | \$75,000 |
| AQUATICS | \$1,000,000 |
| NATURE PLAYGROUND | \$300,000 |
| RESTROOM | \$250,000 |
| SHELTER | \$100,000 |
| DESTINATION SHELTER | \$350,000 |
| FISHING DOCKS | |
| STAGE DOCK | \$150,000 |
| PICKLEBALL | \$150,000 |
| SITE FURNISHING | \$20,000 |
| LANDSCAPE | \$20,000 |
| TOTAL | \$2,535,000 |
| | |



RECOMMENDATIONS





Evaluate facilities that under perform or require excessive maintenance

A. Tennis Court at Bel Aire Park B. Pool at Central Park



Update Playground

a. Accessibilityb Multi-generationalC. Variety of types of play (Nature, Rope, and Fitness)



Recognize/Establish the Recreational Complex as a hub for the community

A. Bring Back Bel Aire Days B. Central Gathering Place in the park C. Investigate addition to the Rec Center

Continue Promotion of Parks and Programming

A. Using Social Media, B. Include the Recreation Complex Under Parks on the Website



15

City of Bel Aire, Kansas

STAFF REPORT

DATE: September 6, 2023

TO: Ty Lasher - City Manager Bel Aire City Council

FROM: Brian Hayes – Recreation Director

RE: Central Park Pool

<u>SUMMARY:</u> Per instructions, staff has assembled information and estimates for pool resurfacing and circulating pump repair of the Central Park Swimming Pool. Additionally, we have partnered with Brad Ward of Midwest Engineering Inc. to assist with the evaluation and future consultation of the facility. Brad has local experience with pool construction and renovation. That experience includes the Wichita YMCA's, USD's 259, 266, & 490, City of Valley Center and Derby Rec Commission just to name a few.

<u>HISTORY:</u> The Central Park Swimming Pool was constructed in 2005 as part of the original phase of the Central Park development. The pool was designed and constructed as a HOA amenity comparable to a large hotel pool. The original plan for the pool was for the Central Park Homeowners Association to take over operation of the facility as the development progressed. Those original intentions never came to be as the homeowners' associations successfully cut ties to the pool in 2019 & 2020.

Construction of the pool basin in 2005 took place during a rainy spring. The plan was to open the pool that summer but the concrete pool bottom failed shortly after it was poured due to suspected groundwater. Needless to say the pool did not open that year. Structural engineers recommended to remove the bad concrete, patch holes, seal cracks, and pour a cap over the affected area which took place in early 2006. The original contract included a plaster surface which was installed and the pool opened for business that Memorial weekend.

Plaster surfaces have an estimated 8-10 year life so the pool was re-plastered in 2016. Again, Mother Nature did not cooperate with a rainy spell before the re-plastering was complete. After the pool opened that year, a large portion of the new plaster bottom failed, again attributed to suspected groundwater. The pool then was closed for about 3 weeks in June while the old plaster floor was removed and replaced.

Areas of concrete deck and coping were also replaced due to deterioration, settling or heaving in 2016 and 2021.



The current pool circulating pump is 7 years old. The original pump was 10 years old when it was replaced and was the second time it failed. It is not uncommon for these pumps to fail when they are over 5 years old.

<u>DISCUSSION</u>: The current plaster surface is now 8 years old and is in need of repair. The surface continues to become porous and is rough in places resulting in maintenance difficulties as well as being rough to the touch. Unfortunately, most concrete/plaster pool surfaces are rough due to their nature. The rough surface is susceptible to algae growth, harder to clean, and sometimes require more chemicals. Pool toes (*see attachment*) is also an issue with plaster pools even with newer surfaces. Truth is when swimmers are in the water for long periods of time, skin becomes tender, and some feet get abrasions. Most of this subsides after their feet become callused. Water shoes can be worn to alleviate this if swimmers so choose.

A 30' long crack appeared in the floor this spring after it was drained to be prepped to open. This will have to be addressed before anything can be done. A water loss test was completed after closing and the pool doesn't seem to be losing or gaining water at this time.

Staff has again had a difficult time obtaining quotes for re-plastering. Two quotes were submitted this time by Mid-West Plastering for \$47,200 with no warranty information provided and Mid America Pool Renovation for \$67,070 with a 5 year limited warranty. Both quotes include crack repair but were sight-unseen so depending on the condition of the plaster when drained could be more.

Mid America Pool Renovation also quoted 2 alternatives as well as options to replace the existing tile. The first alternative is an exposed aggregate finish which is similar to plaster but a bit smoother for \$81,650 with a 5 year limited warranty. Mid America's premier surface Inter-Glass which was additionally quoted for \$111,430 carries a 25 year limited warranty.

2 updated estimates were also received for installation of 60 mil commercial vinyl liners that have limited 10 year warranties. Although we have these liner installation quotes of \$58,675 and \$74,950, there are many unknown costs and variables that need to further be researched by professionals in the field.

The circulating pump motor of the pool failed on August 5th resulting in closing for the summer 2 days early. Atlas Electric deemed the motor to be bad and the pump impellor and diffuser shows signs of wear. Estimates to rebuild the existing pump assembly is \$1500 - \$3500 depending on the condition of internal pump components or a new pump assembly estimate is \$5000.

Central Park Swimming Pool



| Pool Revenue: | 2019 | 2020 | 2021 | 2022 | 2023 |
|-----------------------|-------------|-----------|----------|-------------|-------------|
| HOA Contributions | 20,130 | 4,420 | 0 | 0 | 0 |
| Day Fees | 8,882.50 | 11,997.00 | 8,899.00 | 12,214.00 | 11,464.00 |
| Community Memberships | 5,035 | 8,306 | 10,623 | 9,786 | 12,290 |
| Swim Lessons | 6,510 | 3,260 | 7,680 | 6,370 | 6,621 |
| Rentals | 3,134 | 2,440 | 4,970 | 3,655 | 6,120 |
| Concessions | 1,039 | 0 | 857 | 1,106 | 1,038 |
| Revenue: | \$44,730.50 | \$30,423 | \$33,029 | \$33,131.30 | \$37,532.00 |





MECHANICAL ENGINEERING FEE PROPOSAL

24 August 2023

Mr. Brian Hayes Recreational Director City of Bel Aire 5251 E. 48th Street North Bel Aire, KS 67220

Subject: Swimming Pool 7350 East Central Park Avenue

We offer the following proposal of professional engineering fees and services for your review. We appreciate you reaching out for this opportunity. Midwest Engineering Inc. (MEI) has been involved in many pools in the Wichita area and include the following:

- Greater Wichita YMCA East Branch, West Branch, North Branch, Northwest Branch, South Branch, El Dorado Branch, Newton Branch, Andover Branch, and Camp Hyde.
- USD 259 East HS, West HS, Southeast HS, NE Magnet HS, Northwest HS, North HS, and South HS.
- USD 266 Maize Performance and Aquatics Center.
- Valley Center Recreation Commission (Lyon's Park and the new Rec Center).
- USD 485 Andover HS
- Derby Recreation Center.
- Ponca City, OK, Recreation Aquatic Center (former YMCA).
- Rolling Hills Country Club.

MEi's primary service is mechanical engineering on commercial facilities entailing HVAC and plumbing systems. Our experience with pools has included many new pools in which we have designed the water circulation and filtration systems but also have dealt with restoring existing pools and evaluating existing pools. Northwest HS, Rolling Hills CC, North YMCA (the old Barnacle Bill's outdoor water park), Camp Hyde and the South YMCA outdoor pool have all involved restoration of existing pools. An evaluation of USD 490 El Dorado was recently completed. MEi typically works with Schaefer Architecture, Dudley Williams and Associates structural engineers, along with a few different electrical engineering consultants and even Water's Edge.

General Scope of Services:

- Provide a general assessment of the City's swimming pool.
- The overall condition of the pool will be evaluated based on an visual inspection and reviewal of the history of facility provided by the City.
- Provide general consultation concerning the pool for the City, facilities staff, and/or community groups.
- Provide general review of any proposed modifications to the pool.
- No design work is included or anticipated but items may result in new design work or recommendations of such work.

1210 E. 1st Street, Wichita KS 67214 Ph. 316-262-9300 Fax 316-262-9305



Compensation:

Basic Services as described shall be performed on an Hourly Basis. The majority of the services for this will • be performed by a Design Principal.

> Standard Hourly Billing Rates: \$140.00/Hour

- Design Principal ٠
- Engineer .
- Design Technician .
- CAD Technician
- Clerical

\$120.00/Hour \$80.00/Hour \$70.00/Hour \$40.00/Hour

Invoicing/Terms of Payment:

Invoices will be submitted on a monthly billing basis. Payment on all invoices shall be due within sixty (60) calendar days of receipt.

You may authorize us to proceed with this project by signing where indicated below and returning a copy for our files or by executing an AIA Document "Standard Form of Agreement between Owner and Consultant". Proceeding with work on this project will be considered as an approval of this proposal without a signed document.

We appreciate your business and look forward to working with you on this project. If you have any questions, please contact me at (316) 262-9300.

Sincerely,

Bradley L. Ward, P.E.

C Authorized by:

8/28/23 Date:

1210 E. 1st Street, Wichita KS 67214 Ph. 316-262-9300 Fax 316-262-9305



07 September 2023

To: Brian Hayes Recreation Director City of Bel Aire

From: Brad Ward, PE

Reference: City of Bel Aire Swimming Pool

ASSESSMENT OF EXISTING CONDITIONS

Existing Conditions

The existing pool is an 'L' shaped pool 30'-0" wide and 75'-0" long on each leg with a 4,500 square foot total surface area. The pool was constructed in 2005. The northwest end of the pool is zero entry meeting ADAAG requirements. The pool does not exceed 5'-6" depth and there are no diving boards. The pool was constructed with poured in place concrete with a painted plaster finish, and a concrete deck around the perimeter of the pool. The water circulation system consists of return inlets around the perimeter walls of the pool. The location of the return inlets was not visible at the time of the site visit in August a week after closing the pool because of algae. There are six main drains located on the bottom of the pool and skimmers spaced around the perimeter of the pool for surface drainage. There are underwater lights in the pool walls. The pool deck does drain away from the pool and is in good condition. The main circulation pump failed at the end of the season and is noted to be 260 gpm minimum on the original plans. The pool is considered more of a development/residential style of pool as opposed to a typical commercial pool. Based on standard occupancy capacity requirements the pool could accommodate 100 - 150 people. There is a trench drain between the building and the pool for water drainage away from the building and pool.

From our earlier discussion it is understood that during construction a portion of the pool did heave (concrete lifted up) due to a wet spring. The pool was repaired prior to putting the pool into operation. There is no perimeter foundation drainage system around the pool nor was the pool ballasted to prevent upheaval if the pool is empty. For this type of installation, which is very common, it is recommended to keep a minimum of 2-3 feet of water in the pool at all times, the weight of the water prevents upheaval. For winterization the pool would be drained to below the return inlets to allow the piping from the pump to the pool to drain. Over time a few cracks in the floor have developed and have been repaired, which is common in outdoor pools due to expansion and contraction of the soils and concrete. Likewise the PVC piping may split or pull apart at fittings due to expansion and contraction and this pipe being installed within the frost zone (36″ deep). A section of pipe (and deck) was repaired off the southwest end of the pool a few years ago due to this. It was obvious at the time of the site visit that the pool did not have any leaks.

The water circulation system is fairly simple and standard system using a single circulation pump, basket filter, sand filter, and chemical feeder. The unusual item on this pool is that there are six (6) main drains in the floor, typically there are only two. Standard turnover rate on a public pool is 6-8 hours. The turnover rate is how long it takes to circulate the entire volume of water in the pool through



the filtration system. The turnover rate was not calculated, but the 260 gpm noted on the original plans should be within normal standards on this size of pool. As a note, the State of Kansas does not have any formal design standards for pools, the health department only requires the water quality to be monitored and maintained. Most designer's utilize national design standards if a local or state code doesn't exist. Two items to verify are the grates on the drains do have a lifespan due to a federal law (Virgina Graeme Baker Act) and they may need to be changed out and since the drains are directly piped to the pump there needs to be vacuum breaker emergency shutdown (Vac-A-Lert) installed on the system. Since there are six drains the likelihood of having all the drains blocked is extremely low but the safety does need to be in place.

General Comments

Pools can be constructed in numerous different ways with a variety of different finishes but all require periodical maintenance that, at times, can be fairly expense. Commercial pools require more maintenance than residential pools just because of more people, abuse, and chemical usage. Larger pools are typically poured in place concrete, gunite, or shotcrete with a painted, plaster, or tile finish. Smaller pools can be vinyl, fiberglass, or even stainless steel. Exterior pools experience a lot of different temperature and chemical exposures requiring a little more maintenance than indoor pools. It is not uncommon to have to repaint, patch plaster, or regrout tile every seven (7) years on average. Vinyl liners have a similar lifespan. Circulation pumps have an average lifespan of 7–10 years. Sand filters usually don't require the sand to be changed out as long as normal backwashing occurs. Some of the plastic components (inlets, skimmers, grates, lids, etc.) may have to be changed out periodically due to UV and chemical exposure making the plastic brittle. Since the pool is not usually used after sunset, I would recommend removing the underwater lights and patching the walls when the plaster finish is redone. Underwater lights are a leak waiting to happen. If afterhours swimming is desired I would recommend adding overhead lights around the perimeter of the deck which also will improve security lighting.

Overall the pool is in good condition and has been maintained well. A plaster refinish does need to occur in the next year or two.



Wednesday, July 19, 2023

Brian Hayes City of Bel Aire 5251 East 48th Street North Bel Aire, KS 67220

Dear Brian,

Below please find our updated proposal for resurfacing the plastered zero-entry pool for the City of Bel Aire, KS as discussed. Our scope of work includes the following:

- 1. The pool totals approximately 4,600 square feet (plan and wall areas).
- 2. Lightly prep the surface of the pool (surface repair work is not to exceed 2 total manhours) for the installation of the new 60 mil PVC membrane and terminations.
- 3. Fully adhere an 11-ounce polypropylene felt protection / leveling layer to the entire surface of the pool.
- 4. Custom fit and adhere a premium 60 mil light blue PVC membrane to the entire surface of the previously felted pool. Hot air weld and seal all seams.
- 5. Terminate the membrane using hard PVC strips set into a bed of caulking and fastened onto the top of the walls just below the coping around the perimeter of the pool, and with PVC coated bent metal into the drain in the zero-entry area (PVC membrane to be welded directly onto the PVC coated strips). Finish with a bead of white caulking.
- 6. Where necessary install custom made Type 1 Hard PVC flanges around all penetrations i.e.; skimmers, returns, rope hooks, and drains, and black PVC transition lines as required according to KS state code.
- 7. Install slip-resistant 60 mil PVC membrane in the zero-entry and shallow areas, and white printed depth markers on the top of the pool walls as required according to KS state code.
- 8. Issue a 10 year material warranty (covers PVC membrane material and welds) and a one-year labor workmanship warranty upon payments received in full for all invoiced installation work.

PRICING

The price for the above scope of work is \$ 74,950 (seventy four thousand, nine hundred and fifty dollars) and includes all materials, labor, and travel expenses.

CONDITIONS

- 1. Pool shall be broom clean and empty of water (by others).
- 2. Existing surfaces must be able to accept fasteners.
- 3. Owner is to provide power and unimpeded access to the worksite.
- 4. No bonds, permit, or licensing fees were figured into the bid price.
- 5. Kansas State Davis-Bacon prevailing wage rates were considered in the bid price.
- 6. Owner is to provide for all trash disposal or additional charges to dispose of all waste will be added to the above pricing.
- 7. We strongly suggest all lines should be pressure tested (by others). Any repair work required as a result of the pressure tests is to be performed prior to our arrival.
- 8. No monies were allocated for any repairs or upgrades to the main drains or main drain covers as may be required by the Virginia Graeme Baker Anti Vortex law.
- 9. Only minimal surface prep as previously described is included in the above pricing. Additional surface prep (i.e.: grinding, sanding, patching, rust proofing) will be billed at a rate of \$95 per man hour plus materials in addition to the above if required (ownership will be informed of all surface concerns and shall approve of any additional work prior to it being performed on site).
- 10. The pool will be filled by others, Membrane Concepts will not absorb any costs for water, chemicals or for any pool downtime expenses at any time or for any reason.

TERMS

These Terms and Conditions shall apply to all orders accepted by Membrane Concepts and shall be deemed incorporated in any contract documents. Membrane Concepts is not bound by any additional or different terms proposed by Purchaser in its contract purchase order, conformation, or acknowledgment.

This proposal is valid for 60 days. A deposit of fifty (50%) percent is due with the signed proposal. An additional progress payment of thirty (30%) percent is due at the approximate midpoint of the project. The remaining balance is due immediately upon project completion. A finance charge of 1.5% per month (18% per annum) will be added to all invoices over 30

days. In the event any third parties are employed to collect any outstanding monies owed by said business, the undersigned agrees to pay all reasonable collection costs, including all attorney fees, whether or not litigation has commenced, and all costs of any litigation incurred. The laws of the Commonwealth of Massachusetts and its jurisdiction (Bristol County) shall govern in full over this agreement.

ACCEPTANCE OF PROPOSAL

City of Bel Aire, KS or its agent agrees to the described scope of work, and all conditions and terms as set forth above;

CITY OF BEL AIRE, KS

By _____

Date _____

Sincerely,

An mit

Ron Melbourne General Manager

Membrane Concepts PO Box 51262 New Bedford, MA 02745

Ron@MembraneConcepts.com Office: 508-995-9500 Cell: 508-801-3206



7/20/2023

City of Bel Aire Mr. Brian Hayes Recreation Director 5251 E. 48th St North Bel Aire, KS 67226

Re: Pool Renovation

Dear Mr. Hayes,

Thank you for contacting Mid-America Pool Renovation, Inc. We specialize in swimming pool re-surfacing and repairs, and have over 40 years experience renovating swimming pools.

Our **Major Commercial Reference Lists** are included in this proposal. Feel free to contact any of these references in regards to our reputation, quality of work and warranty services.

Our reference lists include many prestigious establishments. We would be pleased to add City of Bel Aire, Kansas.

Mid-America Pool Renovation, Inc. offers tiling, coping, deck topping, and pool interior resurfacing. In addition to re-plastering, we are the exclusive manufacturer and area applicators of the INTER-GLASS[®] Reinforced Polymeric System, the only authorized reinforced polymeric re-surfacing system for the Host Marriott managed Hotel Group.

Mid-America Pool Renovation, Inc. is fully insured and bondable. We are members of the International Concrete Repair Institute, the Association of Pool & Spa Professionals, the National Plasterers Council, the Waterjet Technology Association, and have an A+ Rating with the Better Business Bureau of Greater Kansas City.

Mid-America Pool Renovation, Inc. is an **Illinois Department of Public Health Pre-Qualified Illinois Swimming Facility Contractor**.

We maintain full insurance coverage and have enclosed a sample Certificate of Insurance.

We enforce a drug-free workplace.

Section I, Item B. 5929 E. 154th Terrace Grandview, MO 64030

816.994.3300 Kansas City 773.278.7349 Chicago 636.537.0108 St. Louis 800.253.7349 Other Areas

816.994.3301 FAX

poolrenovation.com

COMPLETE SWIMMING POOL RENOVATION

- Polymeric Composite Surface Systems Madewell[®] Mainstay[®] Perma-Shield[®] INTER-GLASS[®] Hydro Ester LV Coating
- New Pool Interiors INTER-GLASS® Re-Plastering Sunstone® Diamond Brite® River Rok® Beadcrete® Krystalkrete®
- Deck Re-Surfacing Texture-Dek Kool Deck[®]
- New Tile 100s of Patterns Depth & No Dive
- New Coping Brick Cast Stone Concrete Bullnose
- Water Features
- Structural Repair & Consultation





INTERNATIONAL CONCRETE REPAIR I N S T I T U T E





PRICING SUMMARY (details for each item are in quote body)

| Pool Interior Options | |
|----------------------------------|-------------------------------|
| White Plaster: | \$67,070.00 – 5 Yr Warranty |
| Exposed Aggregate Finish: | \$81,650.00 – 5 Yr Warranty |
| White INTER-GLASS [®] : | \$111,430.00 – 25 Yr Warranty |
| Additional Interior Items | |
| Waterline Tile: | \$23,130.00 |
| Depth Markers: | Included with New Tile |
| Additional Items: | |
| Re-Tile 450 Sqft Beach Entry: | \$27,000.00 |

Note: All construction agreements will contain an additional line item for Mobilization totaling 4% of the contract total.



POOL INTERIOR SURFACES - Alternatives

For most residential and commercial swimming pools, we recommend and offer a choice of two pool interior surfaces. 1) Polymeric INTER-GLASS[®], and 2) Cement-based re-plastering (with pool plaster, or exposed aggregate materials), are both at the pinnacle of their representative categories and known for their proven longevity and reliability.

Pool plaster continues to be the most popular surface used on new concrete pools and residential pools, as well as being the most economical re-surfacing option we offer. For commercial pools, heated pools and spas, pools constructed with panel walls, and pools with structure cracks, the INTER-GLASS[®] Reinforced Polymeric System presents important advantages over pool plaster due to its tolerance to structural cracking and movement, its resistance to pool chemical abuse, and its lengthy service life.

Both pool plaster and INTER-GLASS[®] come in traditional white, but for an additional charge are available in robin's egg blue, natural colors such as sand and charcoal, and special order colors. For outdoor residential pools without lights, INTER-GLASS[®] is also available with MoonGlow, a special surface that absorbs light during the day and glows at night.



REPLASTERING

Cement-based surfaces such as traditional pool plaster or marcite, exposed aggregate (Diamond-Brite, Sunstone, etc), and pebble finishes with either quartz or dolomite aggregates are widely used for new in-ground concrete swimming pools and spas. Pool plaster uses limestone as its aggregate component while exposed aggregate finished use silica quartz as the aggregate in its mix.

Besides being economical, cement-based surfaces are good choices for swimming pools that are kept full of water and always chemically balanced, where stress or structure cracking is not prevalent or expected, and when the pool is not heated.

Some advantages of cement-based linings are:

- Following installation, the pool can be filled almost immediately without a required, dry curing period
- They come in a variety of colors and finishes

Some disadvantages are:

- They must be submerged to avoid shrinkage cracking and delamination
- Their low tensile and flexural strengths make them susceptible to cracking
- Their naturally high alkaline and porous make-up mandate that the pool water chemistry be kept perfectly balanced to avoid reactions to pool chemicals, calcium carbonate growths and metal staining. They increase the pH of the water, have greater chlorine demands, and will affect Total Alkalinity levels.

Re-Surfacing Specifications & Pricing for Re-Plastering

- Clean, environmentally safe 40,000 psi Ultra High Pressure Water Jetting to remove existing paint and loose, hollow or deteriorated sub-surface materials in order to insure the best possible mechanical bond
- Cutting and removing the existing plaster down at least 2" away from the waterline tiling, inlets, lights and other fixtures to achieve a flush finish with the new surface
- Placing contrasting color highlight tiles to demark the edges of all the steps and benches, and to satisfy applicable local codes
- All labor, materials and any clean-up associated with the re-surfacing work, and a 5-year warranty (see below for details)

The price to prepare and re-surface the City of Bel Aire, Kansas **Pool** with white pool plaster is **<u>\$67,070.00</u>**.

The price to resurface with an exposed aggregate finish is **\$81,650.00**.

Section I. Item B.



*This price reflects standard colors only. Blue, Dark, Pearl, or custom colors may be aladditional charge.

Re-Plastering Warranty

Mid-America Pool Renovation, Inc. has 5-year warranty from the date of installation on the new cement-based lining against any flaking, peeling, popping-off or excessive color change providing the pool is maintained chemically balanced and full of water (with proper winterization included as per National Spa & Pool Institute's BASIC POOL & SPA GUIDELINES, 4th edition, instructions for Plaster Finish pools). This warranty only applies to the labor and materials on the newly placed surface material and does not cover any DAMAGE including, but not limited to or from: Defects in the structure including structural or hairline cracking; Vandalism, intentional or accidental abuse, or neglect; Improper acid washes; Stains or discoloration due to, but not limited to, the improper use of chemicals, improperly maintained water chemistry, or any introduction of metals or metal ions into the water; Improper winterization; Hydro-static water pressure; Any acts of God; From any intruder after the plaster crew has left the job site, or from any other action outside the course of normal everyday use and care of the surface lining, or from any other action over which Mid-America Pool Renovation, Inc. has no control. Consequential damages such as, but not limited to, loss of revenue, cost of water, etc., are not covered under warranty.



THE INTER-GLASS® REINFORCED POLYMERIC SYSTEM

Mid-America Pool Renovation, Inc.'s INTER-GLASS[®] Reinforced Polymeric System of surface preparation and base application is the premium of pool re-surfacing choices. Approximately 50% of our residential clients choose INTER-GLASS[®] over a cement-based interior. Approximately 75% of our commercial pool clients choose INTER-GLASS[®] and nearly 90% of our clients with indoor pools choose INTER-GLASS[®].

The INTER-GLASS[®] system offers an excellent surface for concrete, acrylic-wall, and metal pools:

- INTER-GLASS[®] is an inert surface and does not interact with pool chemicals like a cement or painted surface. This is especially important for indoor pools
- The 'silky smooth' yet non-slippery surface is easy to clean and reduces pool chemical usage up to 50%
- The adhesive and sealing qualities of Epoxy Resin produces a placement venue supporting a fully bonded surface, and resulting in making the pool shell stronger
- The INTER-GLASS[®] surface will not be affected if the pool water chemistry periodically falls out of balance
- INTER-GLASS[®] is unaffected by salt chlorine generators
- The seamless, non-porous surface stops chemically treated pool water from reaching the reinforcing steel and causing carbonation, metal corrosion and concrete degradation
- INTER-GLASS[®] cannot shrink-crack, spall or become rough like cement based pool linings
- INTER-GLASS[®] cannot puncture like PVC or other soft-membrane liners, and it cannot blister like pool paint
- INTER-GLASS[®] eliminates the need for future sandblastings, acid washings, liner replacements and painting
- INTER-GLASS[®] is safe for contact with food. INTER-GLASS[®] meets the national specifications of 21 CFR Parts 117.1580, 175.300 and 177.1640 that cover polymeric materials intended for repeated use in contact with food.
- INTER-GLASS[®] is **PVC-FREE**

The INTER-GLASS[®] system is a combination of a hybrid preparation process incorporating <u>sub-surface</u> Protective Barrier System (PBS) technology and including biaxial E-Glass, roving woven, InterSteel (when needed), and a special sealing resin followed by our 6-step surface installation process.

InterSteel is a structural repair method using various aramid fabrics including Kevlar[®] by DuPont (when necessary) in combination with special Type IV sealing resins used extensively around the world to repair structural earthquake damage. This system yields tensile and flexural strengths in the range of 200,000 to 400,000 PSI.

INTER-GLASS® Specifications & Price

- Removal of all hollow lifted areas or blisters
- Surface sanding as needed
- Hi-pressure water blasting (5000psi) to completely clean the prepared surface
- Installation of a penetrating, sub-surface sealing Protective Barrier System
- Stress / structural crack repair as needed
- Placing contrasting color diamond tiles to demark the edges of all the steps and benches, and to satisfy applicable local codes
- All labor, materials and clean-up associated with installation of the INTER-GLASS[®] system
- 25-year Limited manufacturers warranty

The price to prepare and re-surface the City of Bel Aire, Kansas **Pool** with white INTER-GLASS[®] is: **\$111,430.00**.

INTER-GLASS® Warranty Information

The attached Sample copy of the warranty lists all conditions and limitations. Mid-America Pool Renovation, Inc. provides this warranty to the pool owner providing: a) the entire project has been paid in full, b) outdoor pools are winterized per the Association of Pool & Spa Professionals <u>BASIC POOL & SPA GUIDELINES</u>, 4th Edition, instructions for vinyl-lined, or, plaster or painted pools with covers, c) pools are not left drained with the exception of up to 5 days for necessary repairs for those pools not experiencing hydro-static underground water pressure, and d) the pool structure and sub-surface remain sound and intact.

Mid-America Pool Renovation, Inc. produces and installs the INTER-GLASS® system and warranty's both the labor and materials for the warranty period.



WATERLINE TILE

In changing waterline perimeter tiling we offer the option of choosing from our selection of frostproof swimming pool tiles from the major tile distributors across the United States.

To remove the existing tiling, prepare a tile bed, supply and install the frostproof mosaic swimming pool tile of your choice (@ 6" depth) around the **Pool** would cost \$23,130.00 provided it is contracted at the same time as the pool interior.

Please note that installing tile after the new interior has been installed is more difficult and more expensive.

<u>Note</u>: Depth tiles are placed at a minimum of 25-foot intervals around the waterline of commercial pools, and are included in the above price.

You may choose any of the standard ceramic swimming pool tile patterns for this price. Please provide us with your first and second choices as sometimes patterns are not in stock.

Please note that some tiling in the brochures are listed as "Accent", "Trim", or "Deco" tiling and are more expensive and not generally used as perimeter waterline tiling.
 Please inquire with the office on pricing and information on these or any other types of specialty listed or described tiles.

Mid-America Pool Renovation, Inc. guarantees to use only the best recognized products, the most generally aesthetically appealing application techniques, and the most thorough clean-up procedures recognized by our industry in all of our services to produce a beautiful and safe desired result.

If you have filled out and returned one of our pool specification questionnaires, all above quotes are strictly conditional on the accuracy of the information that you have provided to us.

All construction agreements will contain an additional line item for Mobilization totaling 4% of the contract total.

The above prices are valid for a period of 60 days with payment expected upon completion of each contracted phase or as negotiated.

The quoted prices do not reflect Prevailing Wage Scales, costs of Performance Bonds or local or state sales taxes.

The quoted prices are contingent on the use of Mid-America Pool Renovation, Inc.'s modified AIA four (4) page Construction Agreement. Minor changes, additions or modifications to Mid-America Pool Renovation, Inc.'s Agreement are welcome for our review, however all other 'Independent Agreements' including longer AIA Agreements, Supplemental Conditions, Vendor, Service, or Membership required Agreements will be assessed a minimum charge of **\$ 50.00/per page fee** for legal review and legal amendment as required.

This minimum \$ 50.00/per page fee will need to be paid in advance along with the submittal of such an Independent Agreement (s) as noted above.

The quoted prices are contingent on the use of Mid-America Pool Renovation, Inc.'s Construction Agreement. Any and all other additional costs that might be incurred regarding independent Agreements (Contracts, Service Agreements), including membership fees with organizations are not included in the above pricing and will be billed to the Owner as an additional expense.

Thank you for giving us the opportunity to present this quote on your project and I look forward to hearing from you again soon.

Sincerely,

Landon Cele

Landon Cole Project Manager Mid-America Pool Renovation, Inc.

Section I. Item B.



From: Mid-West Plastering LLC

Bill To: City of Bel Aire

12103 W 64th Street Shawnee, KS 66216 918-728-1572 or 785-408-0013 midwestplasteringllc@gmail.co m 5251 E 48th St, Bel Aire, KS 67220

Amount:

Expiration Date:

\$47,200.00

| 8/19/2023 |
|-----------|
|-----------|

| Item | Rate (excl. tax) | Quantity | Total |
|--|---------------------|----------|-------------|
| Replaster Rec Pool with White Plaster Finish (Site unseen estimate) Prep: Cut underneath tile and chip out 2-3inches under tile. Chip around all returns and lights. Chip- out "hollow" spots making sure the pool is free of loose debris. Power wash and acid wash before putting the bonding agent on entire pool. Plaster pool and trowel smooth. | \$28,800.00 | 1 | \$28,800.00 |
| Travel Fee | \$2,400.00 | 1 | \$2,400.00 |
| Plaster Finish Detail | \$1,000.00 | 1 | \$1,000.00 |
| 30' Structural Crack - unseen After plaster prep is completed, access the 30' crack along the belly of the pool. Trouble shoot the number of structural staples needed to install along crack. Install staples and epoxy to a water tight seal. Final price will be determined at the time of repair. | \$15,000.00 | 1 | \$15,000.00 |

35

 Subtotal
 \$47
 Section I, Item B.

 Total
 \$47,200.00

Notes:

This is an estimate. Approval of this estimate, states you have reviewed and agree to our contract and its terms. Necessary changes due to unforeseen or pre-existing conditions unknown or not included in estimate, may necessitate additional work and expense to allow proper performance of the "Work". Upon discovery of any changes, Contractor shall notify Client and inform Client of additional work, time, and expenses necessary to rectify such deficiency as needed to facilitate proper performance of contracted work.

Accepted on:

Accepted by:

Signature:

36



R e n o S y s

July 19, 2023

City of Bel Aire Swimming Pool

RenoSys PVC Membrane Installation

Proposal

Install the liner in the existing pool employing the RenoSys PVC membrane system, including the following components and services:

INSTALLATION OF THE RENOSYS PVC MEMBRANE

- Broom clean pool surface and void it of all loose debris.
- Coat interior of the pool with sanitizing agent. Apply RenoFelt adhesive required.
- Apply RenoFelt 11 (150 mil) to isolate membrane from the pool as required.
- Install the 60 mil RenoSys PVC membrane through hot air welding throughout.
- Termination to be at top of pool wall (below coping/covering tile).
- All penetrations will be terminated with compression flanges.
- Complete additional perimeter caulking, detail work, finish work to make a complete watertight installation.
- Clean site suitable for pool filling and perform final inspection.
- Membrane and all welds shall carry a **10 year limited warranty**.
- Other installation items shall carry a **1 year limited warranty.** (e.g. caulk, fasteners at compression fittings etc...)

Furnish and Install PVC Membrane \$58,675.00

Price is valid for 30 days. Includes minimal surface preparation (8 man hours). Proposal is based on dimensions and pictures submitted. **Payment terms for the contracted work will be paid as follow: 10% upon contract execution, 50% upon start and 50% upon completion. Dumpster is to be furnished by others at no charge to RenoSys Corporation.** Should RenoSys be required to remobilize our crew due to non-readiness of the swimming pool or concealed conditions requiring additional work, then a \$2,500 change order for remobilization will be assessed. All designs and data included and implied within the contents of these documents are proprietary to ARS. ARS will not be held liable based upon inaccurate, unknown or limited information or conditions provided by the purchaser/owner to create enclosed contents. All submitted drawings, details and data are subject to verification, accuracy and approval by the purchaser/owner. No taxes (sales, use, local, county, state, B&O, privilege and/or other applicable taxes), bonds, permits, prevailing or Davis-Bacon wages, or additional fees are included in this estimate.

I have read and understand the information contained on the reverse side of this contract, conditions, installation, and quotation and agree to the terms within.

For Aquatic Renovation Systems, Inc.

Date

For City of Bel Aire, KS

Date

Stewart J. Mart/CEO

Page 1 of 3

Visit us on the web at... "www.renosys.com" RenoSys Corporation

2825 East 55th Place • Indianapolis, IN 46220 Phone: 800.783.7005 • 317.251.0207 Fax: 317.251.0360 • e-mail: "renosys@aol.com"

R



RenoSys

Agreement for Installation of a RenoSys PVC Membrane System

This contract, entered into between Aquatic Renovation Systems, Inc., and "Purchaser" is for the purpose of having ARS furnish and install the RenoSys PVC Membrane System and for additional services or options, if any, as outlined on page #1 of the attached proposal. Pricing is to include the installation of the RenoSys PVC Membrane System in accordance with the standard specifications and technical directives for a RenoSys PVC Membrane System.

This contract is subject to the following terms and conditions:

- The contract sum listed on page #1 covers only the products and services specifically mentioned therein. No modifications, additions, or deletions will be accepted except by written request via re-submission of modifications to the contract scope and/or approved amount authorized by written change order signed by both parties.
- Every effort has been made to be as accurate and complete in the submittal documents and the related scope of work as possible. Verification shall be the
 responsibility of the purchaser during the submittal approval process. No work will proceed without the written approval "sign-off" of the submittal package by the
 purchaser.
- 3) Payment terms for the contracted work will be paid as follows: See page 1.
- All amounts past due shall be subject to a 1.5% service charge per month as to work or services that have been completed to date. Utilization of the pool constitutes substantial completion
- and acceptance of the PVC Membrane System. Aquatic Renovation Systems will invoice for stored material, when applicable.
- 5) Although every effort will be made to meet the delivery and installation requirements, ARS will not be held liable for any delays caused by transportation, strikes, fires, Government entities, acts of God or under any circumstances such as *force majeure*. Please be advised that vagaries in weather can and will affect the installation schedule. Any and all Liquidated or Consequential damages are not part of this contract and ARS shall not be financially penalized for any reason by any or all delays.
- 6) Labor will be performed and invoiced by Aquatic Renovation Systems, Inc.
- 7) Material will be furnished, shipped and invoiced by Poolequip LLC.
- Pricing is provided in US Dollars.
- 9) Should the need for change orders arise from either party, no work will be performed prior to the execution of the change order by both parties. Further, the payment terms of any change order will be fifty percent (50%) upon execution of the change order with the balance due upon completion of said change order; unless other arrangements are agreed upon in writing by both parties.
- 10) No sales, use, local, county, state, B&O, privilege and/or other applicable taxes are included in this proposal, and purchaser agrees to pay all taxes imposed upon seller by state and/or federal regulation as it pertains to this contract. Taxes will be added and paid by purchaser unless a valid Sales Tax Exemption Form is provided. Use tax may still be required to be paid by the purchaser, even if the entity is tax exempt.
- 11) If either party does not comply with the terms and conditions set forth herein, then in addition to all other remedies available to the other party at law or in equity, the non-complying party shall be liable to the other party for its reasonable attorney fees, costs, and expenses incurred in enforcing the terms and conditions of this agreement.
- 12) This agreement and any amendments thereto shall be binding upon and inure to the benefit of the parties, their respective heirs, assigns, personal representatives and/or successors in interest.
- 13) The State Laws of the State of Indiana shall govern this Contract. Purchaser hereby agrees that the State of Indiana and Marion County possesses exclusive jurisdiction to resolve disputes arising under this Contract.
- 14) ARS is not responsible for any consequential or liquidated damages. In addition, damages resulting from any hydrostatic "ground water" conditions or from a leaking recirculation system causing the pool membrane to fail from such damage is not a warranted item. When applicable; existing pool piping, perimeter gutters and hydrostatic ground water testing will be the complete responsibility and cost to the owner.
- 15) ARS agrees to furnish a standard Insurance Certificate listing Purchaser as an additional insured, indicating proof of workmen's compensation coverage, and listing general liability protection limits of at least one million dollars (\$1,000,000.00).
- RenoSys Corporation is not responsible for filling or draining of the swimming pool water; nor will RenoSys Corporation absorb such cost for any reason.
 Please be advised that in the event that the project is cancelled by the owner or owners' representative, 25% of the total contract amount will be assessed to the purchaser.

Specifications and Contract Conditions for a RenoSys PVC Membrane System Installed

Primary pool lining membrane shall be a flexible 60 mil double ply PVC material UV stabilized, and reinforced with internal polyester webbing. The material shall be formulated using anti-fungal agents and manufactured specifically for use in the commercial pool environments. Clients purchasing RenoSys materials are solely responsible for determining the suitability and compatibility of the RenoSys products for their application. RenoSys will not be responsible for materials reaction to water, substrate, soil or pool chemicals.

Geo-textile fabric underlayment of 100% polyester approximately 150 mils thick to isolate and separate the RenoSys PVC Membrane from the pool wall and floor. Depending on field conditions the use of a factory applied of equivalent quality Felt-back membrane product will be utilized. Geo-textile is an "if required" product and may not be applicable on every project. RenoSys shall be the sole agent to determine if Geo-Textile is necessary for your project.

Provide as required PVC coated RenoSys Metal to make for a satisfactory installation. Sanitizing agents to be applied as required onto the pool substrate to discourage microbial growth under the membrane system. Adhesives as required to attach the Geotextile fabric or membrane to the pool, or the membrane to the Geotextile. Flanges of 1/4" Hard White PVC, custom fabricated for use at all membrane penetrations where required.

The PVC membrane liner and liner installation shall be warranted against leakage for a period of (10) years. Deck caulking, concrete work, and any other work shall be warranted for a period of not less than one (1) year or the manufacturers' warranty period, whichever is greater. Pool equipment shall carry the manufacturer's warranty. We propose to provide and install the above system including: sanitizing, adhesives, RenoFelt, RenoSys 60 mil reinforced membrane, all compression flanges, hardware installation, and incidental equipment to make for a satisfactory installation. This quote also includes: general site clean-up and training of the owner's representative in operation and maintenance of the PVC membrane.

ARS shall maintain the right to salvage any fittings, PVC membrane or equipment replaced in the course of executing this installation contract. Standard material overages are supplied for the efficient execution of the project. Any excess material shall remain the property of ARS.

This proposal is based upon an assumption that the pool is of sound substrate suitable for mechanically fastening standard 1/4" to 3/16" sleeve anchors and other drive type fasteners to secure the membrane system at the perimeter and around pool penetrations. Hidden or unforeseen site conditions are to be repaired, if possible, at additional cost to the owner. ARS will execute the change orders prior to commencing work.

Page 2 of 3

Visit us on the web at... "www.renosys.com" RenoSys Corporation

2825 East 55th Place • Indianapolis, IN 46220 Phone: 800.783.7005 • 317.251.0207 Fax: 317.251.0360 • e-mail: "renosys@aol.com"



By entering into this contract, ARS assumes no responsibility for the correctness of the swimming pools depth in any area of the existing pool. The existing depth of the pool, diving hopper and any modifications required due to any misinformation in their regard are the responsibility of the purchaser. It shall remain the owner's responsibility to assure that all depths, safety features, and markings in the pool comply with applicable local and state pool codes.

Warranties for the completed scope of work will go into effect when the project is paid in full. There will be no warranties, or guarantees given, expressed or implied, by ARS, RenoSys Corporation or its agents except those provided in the official issued Warranty, as stated herein. The warranty offered covers only the pool shell membrane (and/or deck surface membrane if included in the contract) and excludes any contracted work associated with an existing perimeter overflow gutter system. In no event will ARS, RenoSys Corporation or its agents be held liable for any consequential or other damages whatsoever unless agreed upon in writing.

Unless other arrangements are made in advance and stipulated as part of this contract; others are responsible for removing, storing and re-installation of all obstructions that would hinder our work. These items include, but are not limited to: bulkheads, ladders, handrails, climbing walls, water features, equipment, furnishings, pool covers, etc...

The use of the pool by the owner, or those authorized to use the pool by the owner, shall constitute final completion and acceptance of the project by the owner. Issues that may arise with the pool subsequent to final completion shall be addressed in accordance with the terms and conditions of the warranty set forth herein. The parties specifically agree that any warranty issue, or a possible controlled leak, such as through a weep hole, shall not be reason for delayed payment of the amounts due under the terms and conditions of the contract.

RenoSys Installation Requirements:

This agreement must be executed and returned with the required "start-up" payment. This is to ascertain your understanding of the scope of work, our quote, and your responsibilities in the successful execution of your project. It is our intention to have your project go smoothly and be completed on schedule and within the budgeted amount. Your informing us of any potential complications before construction begins can save time and money. We sincerely want your project to be a model of success on which we all will look back with pride. Your assistance in accommodating our following needs will help us to better serve you.

Unless otherwise specifically noted in our quotation, ARS is expecting the following services and amenities to be freely available to our crews:

- 1.) Restroom facilities.
- 2.) Water with at least 40 lbs. of pressure within 50 feet of pools.
- 3.) 110 electric service & 230V, 60-amp service (when applicable for metal welding) within 50 feet of pools.
- 4.) Clear and reasonable access to the pool.
- 5.) Pools & pool decks are to be drained and/or generally clean upon arrival of our crew.
- 6.) It is expected that our crews will have complete access to the facility to work unrestricted hours at no additional cost to ARS.
- 7.) Provide parking for our vehicles at no charge to Aquatic Renovation Systems, Inc.

Photos and/or videos may be taken of your project for our own quality internal communication, advertising and marketing purposes. It is to be understood that ARS will be using such photos and videos for general marketing purposes.

Crews are under instructions to accept no direction from anyone onsite unless it is agreed upon in writing prior to work commencing. Please direct all communication regarding scope of work or request modifications to your assigned ARS project manager. Owner shall appoint one individual who will act as the "OWNERS REPRESENTATIVE" to answer questions that may arise.

The RenoSys PVC membrane is a reflective material, and any existing depressions, pits, cracks, or voids may remain visible upon completion.

Unless otherwise noted this quotation does not cover: special conditions, state, local or use taxes, Union affiliates, Davis-Bacon Wages, or differing site conditions from those detailed.



Initial_____

Visit us on the web at... "www.renosys.com" RenoSys Corporation

2825 East 55th Place • Indianapolis, IN 46220 Phone: 800.783.7005 • 317.251.0207 Fax: 317.251.0360 • e-mail: "renosys@aol.com"

https://www.poolsupplyunlimited.com/



EQ Series® high performance commercial pumps are designed for maximum efficiency and quiet operation in every detail. They are the only noncorrosive, all plastic pumps designed exclusively for the commercial pool and water applications market. EQ Series impellers are manufactured for true breakthrough performance, allowing for lower loads and longer motor life. Available with and without strainer pot.

Commercial Plastic pump built specifically for commercial and large residential pools. Pump features extraordinary electrical and hydraulic efficiency that pays premiums in low electrical costs, less wear and tear on critical moving parts, and quiet operation.

Pentair EQ500 Series Premium Efficiency Commercial Pool Pump Without Strainer | NEMA Rated | Single Phase | 230V 5HP | 340019 \$4,967.53

City of Bel Aire, Kansas

Public Works Facility Master Plan

September 07, 2023



Contents

Section 1

| Section 1.1 | Introduction |
|-------------|--------------------------|
| Section 1.2 | Executive Summary |

Section 2 SITE ANALYSIS

| Section 2.1 | Existing Public Works Site |
|-------------|------------------------------|
| Section 2.2 | Sunflower Commerce Park Site |

Section 3 FACILITY PROGRAM

| Section 3.1 | Administration Building Program |
|-------------|--|
| Section 3.2 | Vehicle Maintenance Building Program |
| Section 3.3 | Administration & Vehicle Maintenance Building Floor Plan |
| Section 3.4 | Existing Public Works Building Program & Floor Plan |
| | |

- Section 3.5 Vehicle Storage Building Program & Floor Plan
- Section 3.6 Public Works Facility Elements
- Section 3.7 Current Public Works Equipment / Vehicle List
- Section 3.8 Projected Public Works Equipment / Vehicle Need

Section 4 OPTION ANALYSIS

| Section 4.1 | Existing Public Works Site Development Plan Elements |
|-------------|--|
| Section 4.2 | Existing Public Works Site Development Plan Analysis |
| Section 4.3 | Sunflower Commerce Park Development Plan Elements |
| Section 4.4 | Sunflower Commerce Park Development Plan Analysis |

Section 5 CONCEPTUAL BUDGET SUMMARY

Section 5.1 Section 5.2

Existing Public Works Site Sunflower Commerce Park Site

Acknowledgments

City Council

Jim Benage, Mayor Justin Smith, Council President Emily Hamburg Tyler Dehn John Welch Greg Davied

City Staff

Ty Lasher, City Manager Anne Stephens, City Engineer Marty McGee, Public Works Director Jon Stehman, Public Works

Consultant Team LK Architecture



Draft Submittal: August 09, 2023

Section 1.1

Introduction

The City of Bel Aire, Kansas is located on the northeast boundary of the City of Wichita. One of nineteen cities in Sedgwick County. Bel Aire is the fifth largest community in the county with an estimated population of 8,200. Well-known for its quality of life, low crime rate and close proximity to Wichita, Bel Aire offers a community which many people desire. Bel Aire is also one of the fastest growing cites in Sedgwick County with an average of 100 new residential homes being constructed each year. USD 259 maintains the Northeast Magnet High School and Isely elementary. Two private schools call Bel Aire home being Sunrise Christian Academy and Resurrection Catholic School. The city limits hit K254 on the north, 37th Street on the south, 127th street on the east and Oliver on the west.

The city provides the following traditional governmental services to its citizens: police protection, public works, parks facilities, recreation, sewer utility, water utility, senior center and municipal court services. Bel Aire is half owner in the Chisholm Creek Utility Authority (CCUA) with Park City which provides sewer treatment / water treatment to both cities. Bel Aire receives half its potable water from CCUA and the other half from Wichita with the capability of adding additional water from both sources. Gas service is through Kansas Gas, electric with Evergy, AT & T phone, Waste Connections trash and Cox cable.

The current Public Works facility is located at 4103 North Woodlawn consisting of roughly 7 acres. The current public works building is 32 years old encompassing approximately 7,200 square feet. Due to the new growth occurring on the east side of Bel Aire, it is anticipated that the Public Works Department will require additional equipment, vehicles, shop and facility capacity to accommodate the increased need. With that foresight, the city acquired two lots in Sunflower Commerce Park for future needs. Approximately 13 acres in size. This master plan study looks at the functional and programmatic requirements for the Public Works Department twenty years in the future as well as study the values of locating future public works facilities on both the existing public works complex site and the two lots at Sunflower Commerce Park.

Section 1.2

Executive Summary

This master plan study looks at the future needs of the Bel Aire Public Works Department 20 years into the future. The City of Bel Aire's projected population growth rate is 10 percent per year. Given that criteria, along with insight and direction from the public works director and associated staff, the anticipated expansion of operational needs for the public works department would generally reflect the current operational needs of peer cities like Andover and Derby, Kansas. The operational staff is projected to grow from 9 current staff to 30 total future staff. Consequently, the equipment and facility needs are projected to also increase accordingly. While the future equipment needs are identified later in this report, the future Bel Aire Public Works Complex is projected to need the following physical plant facilities:

- 1. 10,287 square foot administrative facility
- 2. 9,100 square foot vehicle maintenance facility with a 2,270 square foot mezzanine
- 3. 9,000 square foot equipment storage facility with 2,000 square foot covered storage area

Additionally, the complex is project to need the following site amenities and support structures:

- 1. Concrete circulation drives
- 2. Gravel yard
- 3. 8' tall chain-link perimeter fencing
- 4. Rolling security gates
- 5. 1.5 acres debris yard
- 6. 1,500 square foot open-sided pole barn
- 7. New fuel center with underground tanks
- 8. Bulk material storage areas
- 9. Brine production and storage
- 10. Salt storage building
- 11. Concrete yard ramp
- 12. Salt spreader racks
- 13. Generator


Correspondingly, the two proposed site options for future public works operations were evaluated with these operational, equipment and facility requirements in mind.

SITE ANALYSIS

Existing Public Works Site


Address: 4105 N. Woodlawn Blvd. Legal Description: Lot 1, Block 3 Quail Ridge Addition, Bel Aire, Kansas Lot Size: 310,984 SF (7.14 Acres)

- Existing Public Works Building: 7,200 SF
- Material Storage Building: 1,450 SF
- Above Ground Fuel Center
- Bulk Material Storage Areas
- Access to Farmstead & Woodlawn Blvd.
- South Adjacency: Union Pacific Railroad
- North Adjacency: Single-Family Residential
- Floodplain: Zone AE adjacent Railroad Right-of-way
- Zoning: NA
- Parcel has utility services (water Woodlawn, sewer along north property line)
- Water pump station to remain at east end of property
- Property slopes generally from north to south and west to east
- Adjacent residences are between 5 10 feet higher in elevation



SITE ANALYSIS

Existing Public Works Site




SITE ANALYSIS

Sunflower Commerce Park Site

Address: NA

Legal Description: Lot 6, Block B Sunflower Commerce Park Addition, Bel Aire, Kansas Lot Size: 363,308 SF (8.34 Acres)

- Shovel-Ready Site
- Access Webb Road & 53rd Street via 50th Street (Concrete Street)
- North Adjacency: Industrial / Commercial
- South Adjacency: Industrial / Commercial
- West Adjacency: Drainage Reserve (Regional Stormwater Detention)
- Floodplain: NA
- Zoning: Industrial
- Parcel has utility services (water 50th Street, sewer 50th Street)
- Property slopes generally from west to east towards detention area
- Approximately 12' of fall across property



SITE ANALYSIS

Sunflower Commerce Park Site



FACILITY PROGRAM

Administration Building Program

The Public Works administration building will provide for general administration, training and operations of the public works department within one building. Generally, the building shell will be an enhanced metal building frame with a sloped metal roof, metal wall panel and a veneer masonry wainscot. The locker room areas will include masonry wall construction and the general office areas will include standard gypsum and metal stud wall construction. The training room area will be designed with storm shelter qualities and built within the shell of the overall metal building frame. It is anticipated that the administration building will be built immediately adjacent to and connected to the vehicle maintenance buildings.

The building components will include the following square foot areas:

| - | Lobby | 675 |
|--------|--------------------------------|--------|
| - | Reception | 200 |
| - | Administration work area | 200 |
| - | Conference room | 635 |
| - | Six private offices (@ 156 SF) | 936 |
| - | Break room | 435 |
| - | Women's restrooms | 300 |
| - | Men's restrooms | 300 |
| - | Women's locker room | 730 |
| - | Men's locker room | 1,200 |
| - | Laundry | 130 |
| - | Training room | 1,240 |
| - | General storage | 300 |
| - | Janitorial | 220 |
| - | Mechanical/electrical room | 260 |
| - | Building grossing | 3,269 |
| Total: | | 10,300 |

FACILITY PROGRAM

Vehicle Maintenance Building Program


The Public Works vehicle maintenance building will provide for general vehicle and equipment maintenance and operations. Generally, the building shell will be a metal building frame with a sloped metal roof, metal wall panel and limited interior concrete masonry wainscot in vehicle areas. The maintenance support areas will continue the metal building finishes to the interior of the building. The vehicle wash bay will be within an enclosed building envelope. It is anticipated that the vehicle maintenance building will be built immediately adjacent to and connected to the administration building.

The building components will include the following square foot areas:

| - | Four Maintenance Bays | 4,345 |
|--------|-----------------------|--------|
| - | Welding | 355 |
| - | Parts Room | 360 |
| - | Sign Shop | 360 |
| - | Paint Booth | 355 |
| - | Wash Bay | 2,250 |
| - | Mezzanine Storage | 2,270 |
| - | Building grossing | 1,075 |
| | | |
| Total: | | 11,370 |

FACILITY PROGRAM

Administration & Vehicle Maintenance Building Plan



FACILITY PROGRAM

Existing Public Works Building Program

The existing Public Works building will provide for general equipment and vehicle storage at the existing public works campus. Generally, the existing building shell is a metal building frame with a sloped metal roof, metal wall panel. The renovation will include patch and replace damaged metal roof and wall panels as well as the concrete floor. Upgrade the HVAC and plumbing systems as well as power and lighting.


The existing operations areas include standard gypsum and wood stud wall framing. The renovation will include reuse and remodel of the existing operations area with new finishes including wainscot wall tile to add durability to the existing gypsum finishes. The operations area will also receive upgraded HVAC, plumbing, power and lighting systems. The storage mezzanine will receive new durable finishes, lighting and a removable rail system. The renovation will also include the addition of a limited interior concrete masonry wainscot in equipment, shop and vehicle areas. It is anticipated that the existing public works building will remain independent of other structures on the Public Works Complex.

The building components will include the following square foot areas:

| - | Six Storage Bays | 5 <i>,</i> 385 |
|--------|--------------------------------|----------------|
| - | Maintenance Shop | 328 |
| - | Locker Room | 220 |
| - | Restroom | 55 |
| - | Dispatch | 180 |
| - | Breakroom | 263 |
| - | Conference Room | 136 |
| - | Two Private Offices (@ 112 SF) | 224 |
| - | Mezzanine Storage | 990 |
| - | Building grossing | 449 |
| | | |
| Total: | | 8,230 |

FACILITY PROGRAM

Existing Public Works Building Plan



FACILITY PROGRAM

Vehicle Storage Building Program

VEHICLE STORAGE BUILDING PROGRAM

The Public Works vehicle storage building will provide for general vehicle and equipment storage. Generally, the building shell will be a metal building frame with a sloped metal roof, metal wall panel and limited interior concrete masonry wainscot in vehicle areas. It is anticipated that the vehicle storage building will be built independent of other structures on the Public Works Complex.

The building components will include the following square foot areas:

| - | Storage Bay | 9,000 |
|---|-------------|-------|
| | | |


- Covered Storage Bay 2,000

Total:

11,000

FACILITY PROGRAM

Vehicle Storage Building Plan



FACILITY PROGRAM

Public Works Facilities Elements

• Images shown to convey general intent & character of facility components. Final structures & systems will be determined at the time of final design.



Open-Sided Pole Barn Storage



Salt Storage



Brine Production & Storage



Fuel Center

FACILITY PROGRAM

Public Works Facilities Elements

• Images shown to convey general intent & character of facility components. Final structures & systems will be determined at the time of final design.



Bulk Material Storage - Concrete Bin Block



Material & Implement Loading Ramp



Salt Spreader Racks



Automatic Rolling Gates

FACILITY PROGRAM

Current Public Works Equipment / Vehicles

| 1037200866901WesternTruck Snow Plow Blade10422020Pro PlusWesternTruck Snow Plow Blade10432020FSMA X 9 X HYD X SSWesternTruck Material Spreader10402006Buck DandyWater HaulerWater Tank Trailer10172005747-FR200S.E.C.ASewer Cleaner Trailer10141998B600TS.D.P.Small Sewer Cleaner10182006TL100ANew HollandLarge Tractor10212014AR-14MultiquipRoller Compactor10231999MV-156-84-56/3041210MonroeTruck Material Spreader10262013AFM4211LandprideSmall Tractor Mower10192006RC5015LandprideLarge Tractor10122015L4701HSTKubotaSmall Tractor10232008DM10John DeereBackhoe10122003770CHJohn DeereBackhoe10232008DM10John BeanChemical Sprayer10332023HV607InternationalLarge Dump Truck10242015EZ Liner 250GracoPaint Striper103520048X304SSXDUALHYDHendersonTruck Material Spreader103520048X304SSXDUALHYDHendersonTruck Material Spreader103520048X304SSXDUALHYDHendersonTruck Material Spreader10352004F-350FordPaint Striper1006< |
|--|
| 10432020FSMA X 9 X HYD X SSWesternTruck Material Spreader10402006Buck DandyWater HaulerWater Tank Trailer10172005747-FR200S.E.C.ASewer Cleaner Trailer10141998BGOTS.D.P.Small Sewer Cleaner20172100 PlusVactoSewer Truck10182006T1100ANew HollandLarge Tractor10212014AR-14MultiquipRoller Compactor10331999MV-156-84-56/3041210MonroeTruck Material Spreader10262013AFM4211LandprideSmall Tractor Mower10192006RC5015LandprideLarge Tractor Mower10122016310HLSLJohn DeereBackhoe10122003770CHJohn DeereMotor Grader10032023HV607InternationalLarge Dump Truck10042006RS304SSHendersonTruck Material Spreader10332008BX304SSHendersonTruck Material Spreader103420088X304SSHendersonTruck Material Spreader103520048X304SSHendersonTruck Material Spreader10342006F-350FordParks Dump Truck10042007F-550FordSmall Dump Truck10042007F-550FordUtilty Crane Tuck10072014F-150FordSmall Dump Truck10082007F-550F |
| 10402006Buck DandyWater HaulerWater Tank Trailer10172005747-FR200S.E.C.ASewer Cleaner Trailer10141998B600TS.D.P.Small Sewer Cleaner20172100 PlusVactoSewer Truck10182006TL100ANew HollandLarge Tractor10212014AR-14MultiquipRoller Compactor10331999MV-156-84-56/3041210MonroeTruck Material Spreader10262013AFM4211LandprideSmall Tractor Mower10192006RC5015LandprideLarge Tractor Mower10252015L4701HSTKubotaSmall Tractor10422003770CHJohn DeereBackhoe10232008DM10John BeanChemical Sprayer10032023HV607InternationalLarge Dump Truck102420088X304SSHendersonTruck Material Spreader103520048X304SSXDUALHYDHendersonTruck Material Spreader10052015EZ Liner 250GracoPaint Striper10062006F-350FordDirector's Truck10072014F150FordBucket Truck10082007F-550FordUtility Crane Tuck10092020F-550FordUtility Crane Tuck10042007F-550FordHateed Truck10052014F150FordUtility Crane Tuck <tr< td=""></tr<> |
| 10402006Buck DandyWater HaulerWater Tank Trailer10172005747-FR200S.E.C.ASewer Cleaner Trailer10141998B600TS.D.P.Small Sewer Cleaner20172100 PlusVactoSewer Truck10182006TL100ANew HollandLarge Tractor10212014AR-14MultiquipRoller Compactor10331999MV-156-84-56/3041210MonroeTruck Material Spreader10262013AFM4211LandprideSmall Tractor Mower10192006RC5015LandprideLarge Tractor Mower10252015L4701HSTKubotaSmall Tractor10422003770CHJohn DeereBackhoe10232008DM10John BeanChemical Sprayer10032023HV607InternationalLarge Dump Truck102420088X304SSHendersonTruck Material Spreader103520048X304SSXDUALHYDHendersonTruck Material Spreader10052015EZ Liner 250GracoPaint Striper10062006F-350FordDirector's Truck10072014F150FordBucket Truck10082007F-550FordUtility Crane Tuck10092020F-550FordUtility Crane Tuck10042007F-550FordHateed Truck10052014F150FordUtility Crane Tuck <tr< td=""></tr<> |
| 10172005747-FR200S.E.C.ASewer Cleaner Trailer10141998B600TS.D.P.Small Sewer Cleaner20172100 PlusVactoSewer Truck10182006TL100ANew HollandLarge Tractor10212014AR-14MultiquipRoller Compactor10331999MV-156-84-56/3041210MonroeTruck Material Spreader10262013AFM4211LandprideSmall Tractor Mower10192006RC5015LandprideLarge Tractor Mower10252015L4701HSTKubotaSmall Tractor10452016310HLSLJohn DeereBackhoe10122003770CHJohn DeereMctor Grader10032023HV607InternationalLarge Dump Truck100520187400InternationalLarge Dump Truck102420088X304SSHendersonTruck Material Spreader103320048X304SSHendersonTruck Material Spreader10242015EZ Liner 250GracoPaint Striper10062006F-350FordBucket Truck10092020F-550FordMall Murphick10042007F-550FordHatcket Truck10042007F-350FordHatcket Truck10032024L2749AKC604A1ExmarkZero Turn Mower10242015F-250FordHatcket Truck1009 |
| 20172100 PlusVactoSewer Truck10182006TL100ANew HollandLarge Tractor10212014AR-14MultiquipRoller Compactor10331999MV-156-84-56/3041210MonroeTruck Material Spreader10262013AFM4211LandprideSmall Tractor Mower10192006RC5015LandprideLarge Tractor Mower10252015L4701HSTKubotaSmall Tractor10452016310HLSLJohn DeereMotor Grader10232008DM10John BeanChemical Sprayer10032023HV607InternationalLarge Dump Truck102420187400InternationalLarge Dump Truck10252007Spin DoctorHurcoWater Valve Turner103520048X304SSHendersonTruck Material Spreader10352004RX304SSXDUALHYDHendersonTruck Material Spreader10362007F-550FordDirector's Truck10072014F-150FordDirector's Truck10082007F-550FordSmall Dump Truck10092020F-550FordHoor Truck10012015F-250FordHabed Truck10022008F-350FordHabed Truck10042007F-550FordHabed Truck10052018F-350FordHabed Truck10092020F-55 |
| 20172100 PlusVactoSewer Truck10182006TL100ANew HollandLarge Tractor10212014AR-14MultiquipRoller Compactor10331999MV-156-84-56/3041210MonroeTruck Material Spreader10262013AFM4211LandprideSmall Tractor Mower10192006RC5015LandprideLarge Tractor Mower10252015L4701HSTKubotaSmall Tractor10452016310HLSLJohn DeereMotor Grader10232008DM10John BeanChemical Sprayer10032023HV607InternationalLarge Dump Truck102420187400InternationalLarge Dump Truck10252007Spin DoctorHurcoWater Valve Turner103520048X304SSHendersonTruck Material Spreader10352004RX304SSXDUALHYDHendersonTruck Material Spreader10362007F-550FordDirector's Truck10072014F-150FordDirector's Truck10082007F-550FordSmall Dump Truck10092020F-550FordHoor Truck10012015F-250FordHabed Truck10022008F-350FordHabed Truck10042007F-550FordHabed Truck10052018F-350FordHabed Truck10092020F-55 |
| 10212014AR-14MultiquipRoller Compactor10331999MV-156-84-56/3041210MonroeTruck Material Spreader10262013AFM4211LandprideSmall Tractor Mower10192006RC5015LandprideLarge Tractor Mower10252015L4701HSTKubotaSmall Tractor10452016310HLSLJohn DeereBackhoe10122003770CHJohn DeereMotor Grader10232008DM10John BeanChemical Sprayer10032023HV607InternationalLarge Dump Truck100520187400InternationalLarge Dump Truck10222007Spin DoctorHurcoWater Valve Turner103420088X304SSHendersonTruck Material Spreader103520048X304SSXDUALHYDHendersonTruck Material Spreader10242015EZ Liner 250GracoPaint Striper10062006F-350FordBucket Truck10072014F-150FordSmall Dump Truck10082007F-550FordMultiluty Crane Tuck10092020F-550FordMultiluty Crane Tuck10012015F-250FordYende Turck10022008F-350FordYende Turck10042007F-550FordYende Tuck10012015F-250FordYende Turck1002 <t< td=""></t<> |
| 10212014AR-14MultiquipRoler Compactor10331999MV-156-84-56/3041210MonroeTruck Material Spreader10262013AFM4211LandprideSmall Tractor Mower10192006RC5015LandprideLarge Tractor Mower10252015L4701HSTKubotaSmall Tractor10452016310HLSLJohn DeereBackhoe10122003770CHJohn DeereMotor Grader10232008DM10John BeanChemical Sprayer10032023HV607InternationalLarge Dump Truck100520187400InternationalLarge Dump Truck10222007Spin DoctorHurcoWater Valve Turner103420088X304SSHendersonTruck Material Spreader103520048X304SSXDUALHYDHendersonTruck Material Spreader10242015EZ Liner 250GracoPaint Striper10062006F-350FordDirector's Truck10072014F-150FordSmall Dump Truck10082007F-550FordMultilty Crane Tuck10042007F-550FordMultilty Crane Tuck10022008F-350FordYende Turuk10042015F-250FordYende Turuk10042022LZS749AKC604A1ExmarkZero Turn Mower10292009LZAS25KC604ExmarkZero Turn Mower |
| 10331999MV-156-84-56/3041210MonroeTruck Material Spreader10262013AFM4211LandprideSmall Tractor Mower10192006RC5015LandprideLarge Tractor Mower10252015L4701HSTKubotaSmall Tractor10452016310HLSLJohn DeereBackhoe10122003770CHJohn DeereMotor Grader10232008DM10John BeanChemical Sprayer10032023HV607InternationalLarge Dump Truck100520187400InternationalLarge Dump Truck10222007Spin DoctorHurcoWater Valve Turner103420088X304SSHendersonTruck Material Spreader10242015EZ Liner 250GracoPaint Striper10062006F-350FordBucket Truck10072014F.150FordBucket Truck10082007F-550FordSmall Dump Truck10042007F-550FordUtility Crane Tuck10022008F-350FordHated Truck10012015F-250FordFlatbed Truck10022020F-550FordFlatbed Truck10012015F-250FordFlatbed Truck10022020LZS749AKC604A1ExmarkZero Turn Mower10242022LZS749AKC604A1ExmarkZero Turn Mower10252008 |
| 10262013AFM4211LandprideSmall Tractor Mower10192006RC5015LandprideLarge Tractor Mower10252015L4701HSTKubotaSmall Tractor10452016310HLSLJohn DeereBackhoe10122003770CHJohn DeereMotor Grader10032023HV607InternationalLarge Dump Truck100520187400InternationalLarge Dump Truck10222007Spin DoctorHurcoWater Valve Turner103420088X304SSHendersonTruck Material Spreader103520048X304SSDUALHYDHendersonTruck Material Spreader10242015EZ Liner 250GracoPairk S Dump Truck10062006F-350FordDirector's Truck10092014F-150FordBucket Truck10042007F-550FordSmall Dump Truck10022008F-350Ford4 Door Truck10012015F-250FordHated Truck10022008F-350FordFlatbed Truck10022008F-350FordFlatbed Truck10032012LZS749AKC604A1ExmarkZero Turn Mower10242022LZS749AKC604A1ExmarkZero Turn Mower10252008F-350FordFlatbed Truck10012018F-250FordFlatbed Truck10262020LZ |
| 10192006RC5015LandprideLarge Tractor Mower10252015L4701HSTKubotaSmall Tractor10452016310HLSLJohn DeereBackhoe10122003770CHJohn DeereMotor Grader10232008DM10John BeanChemical Sprayer10032023HV607InternationalLarge Dump Truck100520187400InternationalLarge Dump Truck10222007Spin DoctorHurcoWater Valve Turner103420088X304SSHendersonTruck Material Spreader103520048X304SSXDUALHYDHendersonTruck Material Spreader10242015EZ Liner 250GracoParks Dump Truck10062006F-350FordDirector's Truck10082007F-550FordBucket Truck10092020F-550FordWall Wall10012015F-250Ford4 Door Truck10022008F-350FordHatbed Truck10032022LZS749AKC604A1ExmarkZero Turn Mower10242022LZS749AKC604A1ExmarkZero Turn Mower10252008F-350FordStreet Sweeper10012008PelicanElginStreet Sweeper10102008FX30Ditc WitchVacuum Trailer |
| 10252015L4701HSTKubotaSmall Tractor10452016310HLSLJohn DeereBackhoe10122003770CHJohn DeereMotor Grader10232008DM10John BeanChemical Sprayer10032023HV607InternationalLarge Dump Truck100520187400InternationalLarge Dump Truck10222007Spin DoctorHurcoWater Valve Turner103420088X304SSHendersonTruck Material Spreader103520048X304SSXDUALHYDHendersonTruck Material Spreader10242015EZ Liner 250GracoPaint Striper10062006F-350FordDirector's Truck10072014F-150FordBucket Truck10082007F-550FordSmall Dump Truck10092020F-550FordMall Dump Truck10012015F-250Ford4 Door Truck10022008F-350Ford4 Door Truck10022008F-350FordFlatbed Truck10232022LZS749AKC604A1ExmarkZero Turn Mower10242022LZS749AKC604A1ExmarkZero Turn Mower10242022LZS749AKC604A1ExmarkZero Turn Mower10242024LZS749AKC604A1ExmarkZero Turn Mower1025208PelicanElginStreet Sweeper10262008< |
| 10122003770CHJohn DeereMotor Grader10232008DM10John BeanChemical Sprayer10032023HV607InternationalLarge Dump Truck100520187400InternationalLarge Dump Truck10222007Spin DoctorHurcoWater Valve Turner103420088X304SSHendersonTruck Material Spreader103520048X304SSXDUALHYDHendersonTruck Material Spreader10242015EZ Liner 250GracoPaint Striper10062006F-350FordDirector's Truck10072014F-150FordBucket Truck10082007F-550FordSmall Dump Truck10042007F-550FordMoor Truck10052018F-350FordUtility Crane Tuck10042007F-550Ford4 Door Truck10022008F-350Ford4 Door Truck10022008F-350FordHatbed Truck10022009LZS25KC604A1ExmarkZero Turn Mower10242022LZS749AKC604A1ExmarkZero Turn Mower10252008PelicanElginStreet Sweeper10102008PelicanElginStreet Sweeper |
| 10232008DM10John BeanChemical Sprayer10032023HV607InternationalLarge Dump Truck100520187400InternationalLarge Dump Truck10222007Spin DoctorHurcoWater Valve Turner103420088X304SSHendersonTruck Material Spreader103520048X304SSXDUALHYDHendersonTruck Material Spreader10242015EZ Liner 250GracoPaint Striper10062006F-350FordParks Dump Truck10072014F-150FordBucket Truck10082007F-550FordSmall Dump Truck10042007F-550FordUtility Crane Tuck10022008F-350Ford4 Door Truck10022008F-350FordFlatbed Truck10022008F-350FordZero Turn Mower10282022LZS749AKC604A1ExmarkZero Turn Mower10442022LZS749AKC604A1ExmarkZero Turn Mower10102008PelicanElginStreet Sweeper10162008FX30Ditch WitchVacuum Trailer |
| 10032023HV607InternationalLarge Dump Truck100520187400InternationalLarge Dump Truck10222007Spin DoctorHurcoWater Valve Turner103420088X304SSHendersonTruck Material Spreader103520048X304SSXDUALHYDHendersonTruck Material Spreader10242015EZ Liner 250GracoPaint Striper10062006F-350FordDirector's Truck10072014F-150FordDirector's Truck10082007F-550FordBucket Truck10092020F-550FordSmall Dump Truck10012015F-250FordUtility Crane Tuck10022008F-350FordLatbed Truck10022008F-350FordFlatbed Truck10282022LZS749AKC604A1ExmarkZero Turn Mower10442022LZS749AKC604A1ExmarkZero Turn Mower10102008PelicanElginStreet Sweeper10162008FX30Ditch WitchVacuum Trailer |
| 100520187400InternationalLarge Dum Truck10222007Spin DoctorHurcoWater Valve Turner103420088X304SSHendersonTruck Material Spreader103520048X304SSXDUALHYDHendersonTruck Material Spreader10242015EZ Liner 250GracoPaint Striper10062006F-350FordParks Dump Truck10072014F-150FordDirector's Truck10082007F-550FordBucket Truck10092020F-550FordSmall Dump Truck10012015F-250FordUtility Crane Tuck10022008F-350Ford4 Door Truck10022008F-350FordFlatbed Truck10282022LZS749AKC604A1ExmarkZero Turn Mower10442022LZS749AKC604A1ExmarkZero Turn Mower10102008PelicanElginStreet Sweeper10162008FX30Ditch WitchVacuum Trailer |
| 10222007Spin DoctorHurcoWater Valve Turner103420088X304SSHendersonTruck Material Spreader103520048X304SSXDUALHYDHendersonTruck Material Spreader10242015EZ Liner 250GracoPaint Striper10062006F-350FordParks Dump Truck10072014F-150FordDirector's Truck10082007F-550FordBucket Truck10092020F-550FordSmall Dump Truck10012015F-250FordUtility Crane Tuck10022008F-350Ford4 Door Truck10022008F-350FordFlatbed Truck10282022LZS749AKC604A1ExmarkZero Turn Mower10442022LZS749AKC604A1ExmarkZero Turn Mower10102008PelicanElginStreet Sweeper10162008FX30Ditch WitchVacuum Trailer |
| 103420088X304SSHendersonTruck Material Spreader103520048X304SSXDUALHYDHendersonTruck Material Spreader10242015EZ Liner 250GracoPaint Striper10062006F-350FordParks Dump Truck10072014F-150FordDirector's Truck10082007F-550FordBucket Truck10092020F-550FordSmall Dump Truck10012015F-250FordUtility Crane Tuck10022008F-350Ford4 Door Truck10282022LZS749AKC604A1ExmarkZero Turn Mower10442022LZS749AKC604A1ExmarkZero Turn Mower10102008PelicanElginStreet Sweeper10162008FX30Ditch WitchVacuum Trailer |
| 103520048X304SSXDUALHYDHendersonTruck Material Spreader10242015EZ Liner 250GracoPaint Striper10062006F-350FordParks Dump Truck10072014F-150FordDirector's Truck10082007F-550FordBucket Truck10092020F-550FordSmall Dump Truck10042007F-550FordUtility Crane Tuck10012015F-250Ford4 Door Truck10022008F-350FordExmark10292020LZS749AKC604A1ExmarkZero Turn Mower10442022LZS749AKC604A1ExmarkZero Turn Mower10102008PelicanElginStreet Sweeper10162008FX30Ditch WitchVacuum Trailer |
| 1024 2015 EZ Liner 250 Graco Paint Striper 1006 2006 F-350 Ford Parks Dump Truck 1007 2014 F-150 Ford Director's Truck 1008 2007 F-550 Ford Bucket Truck 1009 2020 F-550 Ford Small Dump Truck 1001 2015 F-250 Ford Utility Crane Tuck 1002 2008 F-350 Ford 4 Door Truck 1028 2022 LZS749AKC604A1 Exmark Zero Turn Mower 1029 2009 LZAS25KC604 Exmark Zero Turn Mower 1010 2008 Pelican Elgin Street Sweeper 1016 2008 FX30 Ditch Witch Vacuum Trailer |
| 10062006F-350FordParks Dump Truck10072014F-150FordDirector's Truck10082007F-550FordBucket Truck10092020F-550FordSmall Dump Truck10042007F-550FordUtility Crane Tuck10012015F-250Ford4 Door Truck10022008F-350FordFlatbed Truck10282022LZS749AKC604A1ExmarkZero Turn Mower10442022LZS749AKC604A1ExmarkZero Turn Mower10102008PelicanElginStreet Sweeper10162008FX30Ditch WitchVacuum Trailer |
| 10072014F-150FordDirector's Truck10082007F-550FordBucket Truck10092020F-550FordSmall Dump Truck10042007F-550FordUtility Crane Tuck10012015F-250Ford4 Door Truck10022008F-350FordFlatbed Truck10282022LZS749AKC604A1ExmarkZero Turn Mower10292009LZAS25KC604ExmarkZero Turn Mower10442022LZS749AKC604A1ExmarkZero Turn Mower10102008PelicanElginStreet Sweeper10162008FX30Ditch WitchVacuum Trailer |
| 10082007F-550FordBucket Truck10092020F-550FordSmall Dump Truck10042007F-550FordUtility Crane Tuck10012015F-250Ford4 Door Truck10022008F-350FordFlatbed Truck10282022LZS749AKC604A1ExmarkZero Turn Mower10292009LZAS25KC604ExmarkZero Turn Mower10442022LZS749AKC604A1ExmarkZero Turn Mower10102008PelicanElginStreet Sweeper10162008FX30Ditch WitchVacuum Trailer |
| 10092020F-550FordSmall Dump Truck10042007F-550FordUtility Crane Tuck10012015F-250Ford4 Door Truck10022008F-350FordFlatbed Truck10282022LZS749AKC604A1ExmarkZero Turn Mower10292009LZAS25KC604ExmarkZero Turn Mower10442022LZS749AKC604A1ExmarkZero Turn Mower10102008PelicanElginStreet Sweeper10162008FX30Ditch WitchVacuum Trailer |
| 10042007F-550FordUtility Crane Tuck10012015F-250Ford4 Door Truck10022008F-350FordFlatbed Truck10282022LZS749AKC604A1ExmarkZero Turn Mower10292009LZAS25KC604ExmarkZero Turn Mower10442022LZS749AKC604A1ExmarkZero Turn Mower10102008PelicanElginStreet Sweeper10162008FX30Ditch WitchVacuum Trailer |
| 10012015F-250Ford4 Door Truck10022008F-350FordFlatbed Truck10282022LZS749AKC604A1ExmarkZero Turn Mower10292009LZAS25KC604ExmarkZero Turn Mower10442022LZS749AKC604A1ExmarkZero Turn Mower10102008PelicanElginStreet Sweeper10162008FX30Ditch WitchVacuum Trailer |
| 10022008F-350FordFlatbed Truck10282022LZS749AKC604A1ExmarkZero Turn Mower10292009LZAS25KC604ExmarkZero Turn Mower10442022LZS749AKC604A1ExmarkZero Turn Mower10102008PelicanElginStreet Sweeper10162008FX30Ditch WitchVacuum Trailer |
| 10282022LZS749AKC604A1ExmarkZero Turn Mower10292009LZAS25KC604ExmarkZero Turn Mower10442022LZS749AKC604A1ExmarkZero Turn Mower10102008PelicanElginStreet Sweeper10162008FX30Ditch WitchVacuum Trailer |
| 10292009LZAS25KC604ExmarkZero Turn Mower10442022LZS749AKC604A1ExmarkZero Turn Mower10102008PelicanElginStreet Sweeper10162008FX30Ditch WitchVacuum Trailer |
| 10442022LZS749AKC604A1ExmarkZero Turn Mower10102008PelicanElginStreet Sweeper10162008FX30Ditch WitchVacuum Trailer |
| 10102008PelicanElginStreet Sweeper10162008FX30Ditch WitchVacuum Trailer |
| 10162008FX30Ditch WitchVacuum Trailer |
| |
| 10/1 2018 Hauler 1200 Cushman Utility Cart |
| |
| 1020 2009 SS125-1250 Crafco Crack Sealer |
| 101120223500ChevroletFlat Bed Truck |
| 1013 2004 420D Caterpillar Backhoe |
| 10152019S595BobcatSkid Steer |
| 1030200614 PlanerBobcatRotary Planar |
| 1046 2022 E35i Bobcat Mini Excavator |
| 10472021Patcher IICrafcoMastic Machine |
| 2017 2100 Plus Vactor Sewer Truck |

FACILITY PROGRAM

Projected Additional Public Works Equipment / Vehicles

| Fleet ID | Year | Model | Fleet Name | Category |
|----------|------|----------------|-------------|---------------------|
| | | RC5015 | Landpride | Small Tractor Mower |
| | | RC5015 | Landpride | Small Tractor Mower |
| | | S595 | Bobcat | Skid Steer |
| | | TL100A | New Holland | Tractor |
| | | TL100A | New Holland | Tractor |
| | | 310HLSL | John Deere | Backhoe |
| | | LZS749AKC604A1 | EZ Mark | Zero Turn Mower |
| | | LZS749AKC604A1 | EZ Mark | Zero Turn Mower |
| | | LZS749AKC604A1 | EZ Mark | Zero Turn Mower |
| | | LZS749AKC604A1 | EZ Mark | Zero Turn Mower |
| | | F-350 | Ford | Truck |
| | | F-350 | Ford | Truck |
| | | F-350 | Ford | Truck |
| | | F-350 | Ford | Truck |
| | | F-350 | Ford | Truck |
| | | 26' Unit | | Equipment Trailer |
| | | 24' Unit | | Equipment Trailer |

OPTION ANALYSIS


Section 4.1

Existing Public Works Site Plan

Address: 4105 N. Woodlawn Blvd. Legal Description: Lot 1, Block 3 Quail Ridge Addition, Bel Aire, Kansas Lot Size: 310,984 SF (7.14 Acres)

ELEMENTS

- Retain Existing PW Building & Remodel
- New PW Operations & Maintenance Building
- New Fuel Center Underground Tanks
- Bulk Material Storage Areas
- Brine Production & Storage
- Salt Storage Building
- Open-Sided Pole Barn
- Future Enclosed Storage Building
- 8' Screen Wall North & West Property Line
- 8' Chain-Link Fence South Property
- Rolling Security Gates
- Concrete Yard Ramp
- Debris / Waste Yard 0.35 Acres
- Concrete Pavement & Gravel Yard



Section 4.2

OPTION ANALYSIS

Existing Public Works Site Plan

Address: 4105 N. Woodlawn Blvd. Legal Description: Lot 1, Block 3 Quail Ridge Addition, Bel Aire, Kansas Lot Size: 310,984 SF (7.14 Acres)


<u>ANALYSIS</u>

Site Strengths

- Retain Existing PW Building
- Accessibility of Utilities

Site Weaknesses

- Traffic Issues at Woodlawn & RR Crossing
- Narrow Site Use & Circulation Limitations
- Proximity to Single-Family Residential
- Secondary Security Gate
- Site Size Limitations
- Limited Debris/Waste Area
- Limited Area for On-site Stormwater Detention
- Disruption Due to Construction Activities



OPTION ANALYSIS

Section 4.3


Sunflower Commerce Park Site Plan

Address: NA

Legal Description: Lot 6, Block B Sunflower Commerce Park Addition, Bel Aire, Kansas Lot Size: 363,308 SF (8.34 Acres)

ELEMENTS

- New PW Operations & Maintenance Building
- New Fuel Center Underground Tanks
- Bulk Material Storage Areas
- Brine Production & Storage
- Salt Storage Building
- Open-Sided Pole Barn
- Future Enclosed Storage Building
- 8' Chain-Link Fence
- Rolling Security Gates
- Concrete Yard Ramp
- Debris Yard 1.5 Acres
- Concrete Pavement & Gravel Yard



Section 4.4

OPTION ANALYSIS

Sunflower Commerce Park Site Plan

Address: NA

Legal Description: Lot 6, Block B Sunflower Commerce Park Addition, Bel Aire, Kansas Lot Size: 363,308 SF (8.34 Acres)


<u>ANALYSIS</u>

Site Strengths

- Shovel-Ready Site
- Good Access to Two Arterials via Concrete Street
- Accessibility of Utilities
- Regional Stormwater Detention
- Similar Adjacent Land Uses
- Expandability
- Potential Co-Location of Other City Services
- Can Operate at Current Location during Construction of New Facility
- Allows the Potential Re-use of Existing PW Building & Site for Satellite Operations

Site Weaknesses

Marketability of Property for Sale



Section 5.1 CONCEPTUAL BUDGET SUMMARY

Existing Public Works Site

| SITE: | |
|---|---|
| Site Clearing and Preparation | \$ 179,625.00 |
| Earthwork & Grading | \$ 226,400.00 |
| Utilities | \$ 266,250.00 |
| Pavements | \$ 1,053,740.00 |
| Fences & Walls | |
| | |
| Landscape & Irrigation | \$ 148,150.00 |
| Concrete Site electrical | \$ 50,000.00 |
| Site electrical | \$ 171,500.00 |
| Subtotal | \$ 2,427,190.00 |
| | |
| BUILDINGS: | + |
| Existing Equipment Storage building renovation (8,230 SF) | \$ 658,400.00 |
| New Administration building (10,300 SF) | \$ 3,151,800.00 |
| New Vehicle Maintenance building w/ mezzanine (9,100 SF + 2,270 SF) | \$ 2,343,000.00 |
| <u>New Equipment Storage building (9,000 SF indoor + 2,000 SF outdoor)</u> | \$ 753,000.00 |
| Subtotal | \$ 6,906,200.00 |
| | |
| MISCELLANEOUS STRUCTURES: | |
| Pole Barn Storage building (1,500 SF) | \$ |
| Salt Spreader Racks (2 new) | \$ |
| Fuel Center | \$ 250,000.00 |
| Brine Operation | \$ 250,000.00 |
| Salt Storage Building | \$ 52,500.00 \$ 7,500.00 \$ 250,000.00 \$ 250,000.00 \$ 30,000.00 |
| Building Generator (80 Kw) | \$ 40,000.00 |
| Subtotal | \$ 630,000.00 |
| | |
| SITE/BUILDING STRUCTURES TOTAL | \$ 9,963,390.00 |
| | |
| PROJECT ADMINISTRATION: | |
| General Conditions (10%) | \$ 996,339.00 |
| Overhead & Profit (6%) | |
| Construction Contingency (5%) | \$ 597,803.40 \$ 498,169.50 |
| Escalation/Inflation (8% per year) (1-year) | \$ 797,071.20 |
| Project Administration Subtotal | \$ 2,889,383.10 |
| | + _// |
| Soft costs total (Arch, Civil, Struct., MEP, Survey, Geotech, Permit, Test, Comm) | \$ 896,705.10 |
| | |
| TOTAL PROJECT AMOUNT | \$13,749,478.20 |
| | |
| CONTINGENCIES: | |
| Owner contingency (5%) | \$ 498,169.50 |
| Design contingency (20%) | \$ 1,992,678.00 |
| Total contingency amount | \$ 2,490,847.50 |
| | 646 940 995 79 |
| TOTAL PROJECT BUDGET | \$16,240,325.70 |

Section 5.2 CONCEPTUAL BUDGET SUMMARY

Sunflower Commerce Park Site

| SITE: | |
|---|--|
| Site Clearing and Preparation | \$ 73,250.00 |
| Earthwork & Grading | \$ 226,400.00 |
| Utilities | \$ 220,400.00 \$ 248,250.00 |
| Pavements | \$ 248,250.00 \$ 826,525.00 \$ 117,500.00 \$ 177,190.00 \$ 50,000.00 |
| | \$ 820,525.00 \$ 117,500,00 |
| Fences & Walls | \$ 117,500.00 |
| Landscape & Irrigation | \$ 177,190.00 |
| Concrete | |
| <u>Site electrical</u> | \$ 142,500.00 |
| Subtotal | \$ 1,861,615.00 |
| | |
| BUILDINGS: | |
| New Administration building (10,300 SF) | \$ 3,151,800.00 |
| New Vehicle Maintenance building w/ mezzanine (9,100 SF + 2,270 SF) | \$ 2,343,000.00 |
| <u>New Equipment Storage building (9,000 SF indoor + 2,000 SF outdoor)</u> | \$ 753,000.00 |
| Subtotal | \$ 6,247,800.00 |
| | |
| MISCELLANEOUS STRUCTURES: | |
| Pole Barn Storage building (1,500 SF) | \$ |
| Salt Spreader Racks (2 new) | \$ 7,500.00 |
| Fuel Center | \$ 250,000.00 |
| Brine Operation | \$ 250,000.00 |
| Salt Storage Building | \$ 7,500.00 \$ 250,000.00 \$ 250,000.00 \$ 30,000.00 \$ 40,000.00 |
| Building Generator (80 Kw) | \$ 40,000.00 |
| Subtotal | \$ 630,000.00 |
| | |
| SITE/BUILDING STRUCTURES TOTAL | \$ 8,739,415.00 |
| | |
| PROJECT ADMINISTRATION: | |
| General Conditions (10%) | \$ 873,941.50 |
| Overhead & Profit (6%) | \$ 524,364.90 \$ 436,970.75 |
| Construction Contingency (5%) | |
| Escalation/Inflation (8% per year) (1-year) | <u>\$ 699,153.20</u> |
| Project Administration Subtotal | \$ 2,534,430.35 |
| | |
| Soft costs total (Arch, Civil, Struct., MEP, Survey, Geotech, Permit, Test, Comm) | \$ 786,547.35 |
| | |
| TOTAL PROJECT AMOUNT | \$12,060,392.70 |
| | |
| CONTINGENCIES: | |
| Owner contingency (5%) | \$ 436,970.75 |
| Design contingency (20%) | <u>\$ 1,747,883.00</u> |
| Total contingency amount | \$ 2,184,853.75 |
| | |
| TOTAL PROJECT BUDGET | \$14,245,246.45 |

MANAGERS REPORT

| DATE | September 7, 2023 |
|-------|-------------------------------|
| TO: | Mayor Benage and City Council |
| FROM: | Ty Lasher, City Manager |
| RE: | September 12 Workshop Agenda |

City Parks Study:

The Bel Aire Recreation Complex has never had a formal master plan. Over the years, the current outdoor Rec Complex components were built by forward-thinking volunteers, governing bodies, and staff, without the benefit of adequate budgeting, engineering, and professional design. As a result, outdoor ADA access is minimal. Bel Aire Park is the oldest park and has been updated several times. It was originally built when the city was an improvement district. Currently, the tennis court and basketball surfaces are dilapidated, and the park will become larger due to the current Woodlawn expansion. Central Park is the newest park in the city and discussions are underway to repurpose/expand its components, including possibly adding pickleball courts funded by a local developer. At the December 1, 2023 City Council meeting, the Governing Body selected Landworks Studio to complete a survey and subsequent master plans for the Rec Center, Bel Aire Park and the park in Central Park. Included in your packet are the survey results and master plans. Landworks staff will be at the meeting for a presentation and to answer questions.

Pool:

The Central Park pool was originally built to be a neighborhood pool for Central Park. At that time, Central Park consisted of the current Central Park development as well as Elk Creek. Since the city has been responsible for the debt and the HOA does not have the dues to fund such a pool, the city has operated it as a municipal pool. It typically breaks even but expenses do not include water costs or rec staff time managing and maintaining the pool. The pool was built in 2005 at a cost of \$790,000. The annual debt service is \$41,000 per year and will be paid off in 2030.

The pool sits in a location with a high water table that has caused issues in the past. Currently, the plaster is coming off and there are repairs



that need to be made. Council ranked the pool as #8 on their capital improvement priority list. Discussion included turning the pool into a splash pad. Brian is working with a consultant who has a great amount of knowledge and experience in pool design and maintenance to assess the condition of the current pool and share recommendations for repairs / upgrades. Brian and the consultant will be at the meeting to share their findings.

Public Works Facility Study:

At the June 14, 2022 workshop, staff presented the need for more space at the Public Works facility. The current building is 32 years old and sits on seven acres at Woodlawn and the UP railroad tracks. The shop is 7,200 square feet, contains one small break room, two offices and one restroom for eleven staff. As the city grows and requires more equipment as well as staff, the current facility is quickly shrinking in size. Council toured the facility to get a firsthand view of the site. The PBC owns two lots that total roughly thirteen acres in the Sunflower Commerce Park. The PBC is required to hold these lots until the bonds are paid in full, or 2032. Staff suggested selling the current site and building a larger facility in the Sunflower Commerce Park. In January of this year, the City Council was asked to identify and rank future capital projects. The public works facility was #4. However, there was a question as to whether it was better to expand at the current site or move to a new location. LK Architecture was hired to complete a site analysis of both locations and determine the best option for expansion. Included in the packet is their report. LK staff will be at the meeting for a formal presentation and to answer questions.